It is certified that the existing building Bodhi. Tree EMSchool (name of the building or premises) at ... Sal. ba. b.a. Sthupa, Eluxu High way Near Mai Kanta Township... (address) is having block(s)/Floor(s) as per details below: Detail of Block(s) in Block Block BUILDING SAFETY CERTIFICATE

Detail of Block(s) in	Block	Block	Block	Block	Block	Block
school	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the	~					
Block	2	2				

The building is owned/occupied by Badhs Txee E. M. School. (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Building Safety (Name of Department Govt.) on 15/0.5.25. (date of inspection) in the presence of Maddu S. e.y.u.s.ha, Max Saibaba. Sthupam. (name and addresses of the Manager/Secretary dr his representative) and that the building/premises is fit for occupancy for running school with effect from 1.7. 52025 for a period of .9.1. C. years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1. Nil 2. 3.

4. Issued on 1.7. 1.5. 2.0.2.5. at Jauga reddygudenoy

Name: CH. Ryesh Designation: Assistant Enginew (sly Name & Address of Department/ Office: Municipal of fice, Jeg